

Point-Of-Entry (POE) Hourly Leak Report

Building 4, Apartment 854 on the same hourly water leak report is on all three reports. Repeated Violation, Continuous Violation and Flow Violation. The repeated violation shows that 23 out of 24 hours had water usage greater than 130 gallons, the Continuous Violation report shows water consumption for every hour throughout the day, and the Flow Violation report shows that there was 60 minutes of flow every hour throughout the day. In addition, Building 7, Apartment 840 and Building 2, Apartment 805 both show water consumption for every hour throughout the day. This data allows building management to send maintenance staff to these units to remedy the leaks in each apartment.

H2O Degree Multi Meter Leak Report Diagnostic Report for University Row

Minimum Days over Daily Consumption Threshold: 3

Past Days Examined: 6

Daily Consumption Threshold: 150

Single Day High Use Hot Threshold: 500

Single Day High Use Cold Threshold: 250

Point of Entry Leaks (2 of 152)	Hourly Water Leaks (5)	Overconsumption (1 of 152)	Property History	Summary Matrix
---------------------------------	------------------------	----------------------------	------------------	----------------

Repeated Violation (RV) Water Meters

Building	Apt	Serial Number	Details Link	Location	Number of High Usage Hours
4	854	0000D6F000C0159A4	Details	Main Feed Single	23

Continuous Violation (CV) Water Meters

Building	Apt	Serial Number	Details Link	Location	Number of High Usage Hours
7	840	00006F000C016C32	Details	Main Feed Single	141
4	854	00006F000C0159A4	Details	Main Feed Single	3135
2	805	00006F000C01299E	Details	Main Feed Single	155

Flow Violation (FV) Water Meters

Building	Apt	Serial Number	Details Link	Location	Number of High Usage Hours
4	854	00006F000C0159A4	Details	Main Feed Single	23

Point-Of-Entry (POE) Over Consumption Report

This report provides building management and maintenance with information on apartments that have higher than typical water usage. This report allows management to easily identify apartments that need maintenance to address potential leaks and water waste.

Point of Entry Leaks (2 of 152)	Hourly Water Leaks (5)	Overconsumption (1 of 152)	Property History	Summary Matrix
---------------------------------	------------------------	----------------------------	------------------	----------------

Overconsumption- Prepared on 06/02/2017 for 06/01-2017 - [Output to Excel](#)

Building	Apt	Br/Bath	Serial Number	Single Day Use	Four of Five	Single Day Gallons	Single Day Events	Single Day Flow Mins	30 Day Gallons	30 Day ADC Gallons	Leak N of Last 90 Days	OverCon N of Last 90 Days
8	826	3/2	000D.6F00.0C01.0AB6		Yes (>252)	228	209	101	7,247	242		9